



WireCutter



Foaming Acidic Cleaner/Brightener for Wheels, Rims & Tires

for Tunnels, Manual Cleaning & Pressure Washing

A foaming acidic detergent formulated to immediately remove oxidation, carbon residue, road film and grime from wire wheels, spoked rims, mag wheels and most other tire and wheel surfaces. Also great for trucks and trailers. Provides instant cleaning and brightening of aluminum and alloy materials. Penetrates and dissolves brake dust, road film, metal oxidation and other soils on aluminum or chrome plated wheel rims and hub caps. High foaming for prolonged cling on vertical surfaces. Rinses completely.

Directions for Use

Tunnel Car Washes: For automatic in-line spray on/rinse off car wash operations, apply this product at a dilution ratio of 20-40:1 (approximately 3-6 ounces per gallon of water). Solution strength may be adjusted to meet individual circumstances. Consult equipment manufacturer's directions for usage procedures. Follow application of this product with prompt scrubbing and a thorough rinsing. Do not allow detergent or solutions to dry on wheels.

Manual Cleaning: For manually or brush cleaning rims. wheels and tires, dilute 6-12 ounces of this product per gallon of warm water. Spray directly onto surfaces with a coarse spray pattern (avoid mist-type sprayers). Using a soft, natural bristle brush, apply solution to surfaces, agitate. Work in small areas at a time to prevent chemical from drying on surfaces. Allow 1-2 minutes for soil penetration and oxidation removal, then rinse completely with clean water. Do not allow to dry on wheels.

Pressure Washing: Inject this product at 20-40:1 through pressure washing equipment. For best results, apply solution at low pressure to dry surfaces--do not pre-wet. Allow several minutes for detergent to penetrate and dissolve soils, then rinse with hot, high-pressure water. Rinse overspray areas as well. On truck panels, work from the bottom up. Do not allow chemical to dry on surfaces, especially glass.

Safety Reminder

Consult product label and Safety Data Sheet (SDS) before use. SDS's may be downloaded from www.crown-chem.com.



4701 W. 136th St. • Crestwood, IL 60418 tel (708) 371-6990 • (800) 672-4065 fax (708) 371-6992 www.crown-chem.com



RET

Technical Specifications

Appearance Odor pH (1% solution, 22°C) Foaming Flash Point Bulk Density (lbs/gal, 22°C) Stability Range Free Alkalinity (as Na₂O) Solubility (in H₂O, 22°C) Acid Type(s)

Product Number

86505	
86515	
86530	
86555	

Purple Liquid Cherry <2.0 High None 9.15±0.1 50-100°F None 100% ABF, Phosphoric

Packaging

5 gal. pail 15 gal. drum 30 gal. drum 55 gal. drum

